

WORKING PROCESS FOR FLASKING

1. INVESTING: Mixing time within 7 minutes and allow flasks to set at least 1.30 – 2 hours

2. STEAM DEWAXING: Load flasks into a preheated steam dewaxer and dewax for 45 minutes to 1 hour. Leaving flasks in steam dewaxer longer than 1 hour can result in water marks or investment breakdown.

Transfer flasks immediately to a preheated burn out oven set at 150 °C, do not allow flasks to cool down.

3. BURNOUT CYCLE :

90 °C	1 hours.
150 C	1-2 hours.
300 °C	1-2 hours.
500 C	1-2 hours.
730 - 750 ്C	6-8 hours.
Casting temperature	1-2 hours.

4. Please see the instruction sheet of each alloy for graining temperature the fine gold/silver with alloy and Casting Temperature and Flask Temperature.

Representative Office: UNITED PM (THAILAND) CO., LTD.

467/7 2nd Floor, Mahatun Rama 3 Center, Rama 3 Road, Bang Khlo, Bang Kho Leam, Bangkok. 10120, Thailand.